

**ABSTRACT**

A laser processing machine includes a beam guiding chamber, a gas supply for flushing the beam guiding chamber, and a pressure relief valve coupled to the beam guiding chamber for releasing the flushing gas from the beam guiding chamber.

5

10

15

20

25